Storage of idle Saga loggers

To ensure optimal store of Saga loggers

Good cellular connection:
The device always communicates with the cloud for data and firmware updates, even when idle.

Location:
Avoid storing the Saga Loggers in metal enclosures or areas where cellular connection is poor.

Temperature:
Ensure that the ambient temperature is between 0°C and 25°C (32°F and 77°F).

Charge:
Fully charge the logger if the logger is intended to be stored for more than 3 months.

Battery health:
Never store a device with low battery.

Humidity:
Keep the relative humidity below 80%.

FIFO:
Remember of the FIFO (First-In, First-Out) method to reduce the time a Saga Logger spends in storage.

If the above is not followed, the battery health of the Saga Logger may be compromised.

Controlant

© Copyright 2023 Controlant, Inc. All rights reserved. Any disclosure, copying, distribution, posting, or use of the information contained in this document is prohibited.